


Graham/257th Bridge Strengthening // Construction Updates

- Completed Work:
 - Provide steel columns at the construction joints located along bent caps
 - Repair cracking along beams
- Upcoming Work (est. June 2024):
 - Replace above deck bridge joints





Graham/257th Bridge Strengthening // Construction Updates



