

EXHIBIT 15



Exhibit 15 - Photo A



Water streaming across road

West end of culvert in this area

Distressed Road Section

Exhibit 15 - Photo B



Source of Water
across road



Exhibit 15 - Photo C

Exhibit 15 - Photo D



**Area silting in against fence
due to water running across
road. Eventually the slope
may fail due to this load**

Exhibit 15 - Photo E



Exhibit 15 - Photo F





Slide area on 2/26/2021

Exhibit 15 - Photo G



Exhibit 15 - Photo H