


Columbia Gorge Tourism Alliance

Historic Columbia River Highway Waterfall Corridor Disability Audit

Purpose:
Inventory Accessibility for Visitors
to the Waterfall Corridor
by
People with Disabilities,
visible or invisible

Our full report is
not completed as of today,
this is a visual tease of what is in the
report and not intended to be a
detailed representation of
our final report.

October 12, 2022
A. J. Zelada



We created forms
We gathered People
from the Disability Rights of Oregon
We arranged transportation via
Sasquatch Transportation

Shepard's Dell Falls



Amenities

- Waterfall View from Transit Path View
- Restrooms None
- Parking None
- Picnic None
- Transit Door exit
- Sitting

Latourell Falls



Amenities

- Waterfall View from Transit Path View
- Restrooms ADA Wide single multiple None
- Parking ADA None
- Picnic None
- Transit Safe exit
- Sitting None



Inventory of Barriers fell into Primary Issues and Barriers

Primary Concern was Where are the bathrooms and are they accessible

Information about each waterfall site needs to be detailed, (more than an icon)



Restrooms, some does not allow Wheelchair (WC) access

Amenties: picnic table access will not allow WC access to table

Trail damage secondary to weathering

Transit stops : Unable to park van off highway travel lane; no accessory adjacent lane to allow disembarking

Ramps cause lengthy traversing of both travel lanes



